



BATO 6536 USER MANUAL

6W COB WORK LIGHT



General Safety Instructions:

1. Never look directly into the LED light Source.
2. Must only be used on flat, stable surfaces.
3. Must not be immersed in water or other liquids.
4. Must not be operated with wet hands
5. Must never be covered.
6. Must never be operated with an open housing, missing or damaged wiring compartment, or missing or damaged lens.
7. Must never be sprayed or cleaned using a steam pressure cleaner since this can damage the insulation and seals.
8. Must never be repaired by the user, repairs must only be carried out by the manufacturer or an authorized service representative.

Features:

Dimmable brightness: 60-700 lumens
180° + 360° rotating bottom
Magnet and hook at the bottom
Type-C Charging 5V-1A
IP44

Technical Data:

LED: 6W COB/1W Torch
Brightness: COB: 60-700 lumens
Torch: 100 lumens
Battery: Li-ion 3.7V 2600mAh
Working Time: COB: 1.5-15 hrs
Torch: 11 hrs
Charging Time: 4 hrs

Commissioning:

Rotate the switch to the brightness needed from 60-700 lumens.
Press the Torch button to turn ON/ turn off the torch.

Note:

All light are partially charged when delivered.
Charge the product before use fully.
Please do not use the light when charging.
Please do not use a modified or damaged charger.
Please do not leave the lamp be in charging over 24 hours.
Please do not disassemble the lamp.
Please recharge the lamp every six months when in stock.

Cleaning:

Allow the light to cool down sufficiently!
Clean with a dry or slightly moist, clean, lint-free cloth and a mild detergent if required. Do not use cleaners that contain abrasives or solvents.