

BATO 65106 USER MANUAL

6W COB WORK LIGHT

General Safety Instructions:

- 1. Never look directly into the LED light Source.
- 2. Must only be used on flat, stable surfaces.
- 3. Must not be immersed in water or other liquids.
- 4. Must not be operated with wet hands.
- 5. Must never be covered.
- 6. Must never be operated with an open housing, missing or damaged wiring compartment, or missing or damaged lens.
- 7. Must never be sprayed or clea ned using a steam pressure oleaner since this can damage the insulation and seals.
- 8. Must never be repaired by the user, repairs must only be carried out by the manufacturer or an authorized service representative.

Features:

180° bendable + 180° rotation lamp body

Magnet and hook at the bottom

Micro USB Charging 5V-1A

IP65 IK07

Technical Data:

LED: 6W COB/1W Torch

Brightness: COB: 600/300 lumens

Torch: 100lumens

Battery: Li-ion 3.7V 2600mAh Working Time: COB: 2/4 hrs

Torch: 9 hrs

Charging Time: 4 hrs

Commissioning:

The light has four switching stage. Press once on the On/Off switch to go to the next setting, the following setting are possible: COB Full power-COB half power-Torch-OFF

Note:

All light are partially charged when dellvered.

Charge the product before use fully.

Please do not use the light when charging.

Please do not use a modified or damaged charger.

Please do not leave the lamp be in charging over 24 hours.

Please do not disassemble the lamp.

Please recharge the lamp every six months when in stock.

Cleaning:

Allow the light to cool down sufficiently!

Clean with a dry or slightly moist, clean, lint-free cloth and a mild detergent if required. Do not use cleaners that contain abrasives or solvents.