



BGS Glow Plug Removal Tool Set | M10 x 1.0

- ensures the correct removal of burned-in, corroded or broken-off glow plugs
- allows repairing of the glow plug retaining thread without removing the cylinder head
- defective original thread M10 x 1 is repaired by insertion of a new threaded sleeve
- suitable for Mercedes-Benz CDI-engines OM 611, 612, 613, 628, 646 (not EVO), 647, 648

scope of delivery:

- puller and sliding hammer for removing of stuck and broken glow plugs
- reamers for reaming of the defective thread
- tap M10 x 1 and M12 x 1
- centering sleeve for reamers and taps
- special step drills and taps for removal of broken glow plugs
- 12 thread repair sleeves M12 x 1 to M10 x 1
- compressed air adaptor

Weight: 3,820 kg.