



BGS Reamer Set | for ABS Sensor Holes | 8 pcs.

- for cleaning the ABS sensor hole in the wheel bearing housing
- removes dirt, rust and other corrosion particles
- special twist drill for drilling out tightly fixed sensors
- ensures precise position of the sensor
- prevents damages to the new ABS sensor due to incorrect installation, insertion, etc.

suitable for following vehicle models:

- Audi A3 (8P), Q3 (8U), TT (8J)
- Seat Altea + XL, Ibiza, Leon, Toledo3
- Škoda Fabia, Octavia (1Z), Superb (3T), Yeti > 2010
- Volkswagen Golf 6 Beetle > 2011, Golf 5, Jetta 3 + 4, Passat (3C), Lupo, Polo 9N, Scirocco > 2009, Sharan > 2010, T5, Tiguan (5N), Touran > 2005
- Opel Insignia

scope of delivery:

- 1 flexible ratchet | lockable | external square 6.3 mm (1/4") (BGS 25130)
- 1 twist drill, M10 x 133 mm
- 1 reamer Ø 10 x 150 mm
- 1 reamer Ø 11 x 70 mm
- 1 reamer Ø 14 x 32 mm
- 1 reamer Ø 15 x 23 mm
- 1 reamer Ø 18 x 23 mm
- 1 reamer Ø 18 x 34 mm

Weight: 0,861 kg.