



BGS Engine Timing Tool Set | for PSA 1.8, 2.0 16V Petrol

- contains important tools for checking and adjusting the engine timing after replacing the timing belt and engine repairs

suitable for the following models:

- Citroen C5 1.8/2.0 HPi (2002 - 2005) Xsara 2.0 16V (2002 - 2005) Xsara, Picasso 1.8/2.0 16V (2002 - 2005)
- Peugeot 406 1.8 16V (2000 - 2004), 807 2.0 16V (2002 - 2005)
- engine codes 6FZ (EW7J4) FRN (EW10J4 / L4 / 5) RLZ (EW10D)

scope of delivery:

- tensioner locking tool, to be used as OEM 0189S2
- tool for tensioner, to be used as OEM 0178E, 5711TE, 178J/J2
- tool for tensioner, to be used as OEM 0188J2
- adjustment tool for clamping unit, to be used as OEM 0189S1
- locking pins, to be used as OEM 0132AB / 0194A / 0178D
- locking pin, to be used as OEM 0194B
- locking pin, to be used as OEM 0188M
- locking pin, to be used as OEM 0189B
- flywheel locking tool, to be used as OEM 0189R
- locking tool for tensioner, to be used as OEM 7017TR / 0153U
- adjustment tool for crankshaft wheel, to be used as OEM 0188AH

Weight: 1,655 kg.